

## Steps to put on personal protective equipment (PPE)


The dressing and undressing of PPE should be supervised by another trained member of the team. **3** Gather all the necessary items of PPE beforehand. Put on the scrub suit in the changing room.




4 Put on rubber boots. If not available, make sure you have closed, puncture and fluid resistant shoes and put on overshoes.



OR, IF BOOTS UNAVAILABLE




5 Place the impermeable gown over the scrubs.



6 Put on face protection:6a Put on a medical mask.




**6b** Put on goggles or a face shield.



7 If available, put a head cover on at this time.



8 Perform hand hygiene.




9 Put on gloves\* (over cuff).



10 If an impermeable gown is not available, place waterproof





## While wearing PPE:

- Avoid touching or adjusting PPE Change gloves between patients
- Remove gloves if they become torn or damaged
- Perform hand hygiene before putting on new gloves

\* Use *double gloves* if any strenuous activity (e.g. carrying a patient or handling a dead body) or tasks in which contact with blood and body fluids are anticipated. Use *heavy duty/rubber gloves* for environmental cleaning and waste management.



All reasonable precautions have been taken by the World Health Organization to verify the information contained in this publication. However, the published material is being distributed without warranty of any kind, either expressed or implied. The responsibility for the interpretation and use of the material lies with the reader. In no event shall the World Health Organization be liable for damages arising from its use.